

From the holdings of  
**Western Archives, Western University**

November 1st/1916. Machinery idle for want of Blanks.

- 1 - Cutting off closed end No.50, Turning Mill.
- 3 - " " open ends Pipe Machines
- 6 - Rough turning No.326 - 45 - 31 (2) - 345 (2) lathes. A Lathe bed with two head stocks.
- 8 - Boring No.333,332,331,334,220,161,325,324. Gisholts.
- 2 - Centering Machines